

COMPLETION REPORT

1	Name of the work	Removal of debris & dislting of drains in Dasarahalli in ward no. 15 Dasarahalli sub division.		
2	Sanctioned Estimate No. & Date	EE/00/TS/93/16-17 dated 10-01-17		
3	Head of Account which is chargeable	p-code 1771		
4	Instrument Order NO. & Date	EE/AD/00/69/17-18 dated 11-05-17		
5	Name Of Contractor	Sri. N. Shivananda, No. 35, 2nd cross, 1st A Main road, Defiance colony, Bagalagunte, Bangalore.		
6	Time Stipulated for Completion of work	90 days		
a				
b	Delay in Exculation of Work			
7	Measurement recorded in	MB NO 1713 /12-13 page NO 17125 to 171255/2		
8	Check Measurement of the Asst	MB NO 1713 /12-13 page NO 17125 to 171255/2		
9	Name of the office/official in charge of the work	AEE (BSD) (OSD)		
10	a) Asst. Eng/junior Eng	D. S. Mangunath		
	b) Asst. Exe Engineer	Shivakumar Odaga		
Sanctioned Estimate Amout		Amout Claims As per Actually Vide As per bills	Excess	Savings
12-00		933816-A	—	266184-00

- 1) Certified that the above work has been completed within the stipulated time noted in the
- 2) Certified that the contractor has delayed and completed the work for which necessary fine recovered
- 3) Certified that the above work has been executed by the contractor satisfactory in


ASSISTANT ENGINEER.


EXECUTIVE ENGINEER.

Bruhat Bangalore Mahanagara Palike,

Dasarahalli Division, Bangalore-571


ASSIATANT EXECUTIVE ENGINEER

ಬಿ.ದಾಸರಹಳ್ಳಿ, ಉಪ-ವಿಭಾಗ

ಜ್ಞಾನಗಂಗಾಂಟಿ, ಬಿಜಿಎಂಪಿ

-ಸಹಾಯಕ